

# SERVICE NEWS LETTER 067

**DATE:** JANUARY 12, 2009  
**TO:** UD TRUCK DEALER SERVICE MANAGER  
**FROM:** SERVICE OPERATIONS DEPARTMENT  
FILE IN THE POLICY SECTION OF THE TECHNICAL BULLETIN BINDER

## 2008~2009 MODEL YEAR ENGINE OIL CAPACITY LEVELS

### PURPOSE

To advise that the engine oil capacity has changed for the 2008~2009 model year UD Trucks. Reports from the field have been received of "Excessive Crankcase Oil Level" due to technicians using the earlier 2005~2007 model year engine oil capacity recommendations.

### CHANGE NOTICE

With the introduction of the Diesel Particulate Filter (DPF) and the closed crankcase ventilation system on the 2008~2009 J05 and J08 engines, the engine oil refill capacity was decreased.

- Refer to the table below or appropriate model year service manual for approximate engine oil refill capacities.**

Engine Type		Approximate Refill Capacities
J05	With oil filter	10 US quarts
	Without oil filter	8 1/2 US quarts
J08	With oil filter	13 2/5 US quarts
	Without oil filter	11 3/5 US quarts

**WARNING:** Overfilling the engine oil can damage the Closed Crankcase Ventilation System and/or the Diesel Particulate Filter.

THE INFORMATION CONTAINED IN THIS BULLETIN SHOULD NOT BE INTERPRETED AS THE BASIS FOR WARRANTY CLAIMS

FOR THE INDICATED PERSONNEL BELOW, PLEASE READ, INITIAL, AND ROUTE TO THE FOLLOWING:

<input checked="" type="checkbox"/>	SERVICE MANAGER	<input checked="" type="checkbox"/>	WARRANTY MANAGER	<input checked="" type="checkbox"/>	SERVICE TECHNICIANS INITIAL BELOW:		
<input checked="" type="checkbox"/>	PARTS MANAGER	<input checked="" type="checkbox"/>	SHOP FOREMAN				